

25X1

SECRET

Copy I of 8.

9 February 1956

25X1

Construction Required

25X1

25X1

25X1

25X1

1. The list which follows represents estimates of construction required [redacted]. This list is based upon facilities requirements of Detachment A [redacted] and a support detachment (approximately [redacted] personnel) consisting of either SAC and/or indigenous personnel. Items marked with an asterisk must be revised upwards should the total base complement exceed [redacted].

2. Estimates are based upon availability of Butler and/or Quonset type construction.

Poss hall	Capability of feeding 200 personnel
Food storage	200 sq.ft. roofer space
Administration	1000 sq.ft.
Det. A Garage	4000 sq.ft.
Base Supply	4000 sq.ft.
Communications Area (transmitting site)	320 sq.ft.
Communications Area (receiving site)	960 sq.ft.
* File and Equipment storage	960 sq.ft.
* Photographic Laboratory	960 sq.ft.
* Electronics Lab. #1	960 sq.ft.
* Electronics Lab. #2	480 sq.ft.
Communications Repair	400 sq.ft.
Operations	2000 sq.ft.
Maintenance Shop	960 sq.ft.
* Aero Medical and Dispensary	App. 2000 sq.ft.
Hangars	* 22000 sq.ft.

38

080180100


e4e0000

CIA

25X1

- 2 -

Cy 7 of 8.



Two Run-up pads To be constructed in accordance with specifications.

Security 460 sq.ft.

3. The following additional facilities must be made available:

(1) Tower and aids to navigation to include VHF, VHF/DF, and a low-frequency beacon.

(2) Fuel storage for JH-4 and LPIA.

(3) Water Approximately 30,000 gal. daily

(4) 110V., 60 cycle, AC Power 300 KW

(5) 28V., DC 25 KW

(6) 115V., 400 cycle, 3-phase 60 KW

4. Other items that will be required, but of which no details can be given now include:

(1) Security fencing Amount to be determined by size of area.

(2) Access ways and ramps between hangar and taxiway

Amount to be determined by location of hangar in relation to existing airports.

5. It is understood that billeting by both personnel of Detachment 4 and support units will be accomplished by renting houses on the open market. However, an additional mess hall or mess facilities will be required at a downtown location to serve breakfast and supper.

6. Items marked with an asterisk will require temperature and/or humidity control-specifications of which will vary. These specifications will be furnished at a later date.

25X1

25X1

25X1

25X1

WAW:hps (9 Feb 56)

Dist: Orig & 1-Addressee

Lt. Col.

USAF

com-E.M.D. cy 4

-10, cy 5

cy 4

cy 6 - Chrono, cy 7 - Read., cy 8

080180100

0200000